

Inspection No:	INSP23121269
Inspection Date:	12/05/2023
Inspection Time:	0
Inspected By:	McCartney, John

SALISBURY FD FIRE INSPECTION REPORT



Inspection and Compliance Orders			
Facility:	ROTARY CLUB INTERNATIONAL	Address:	300 West LIBERTY Street
Phone:	919-691-2323	City:	SALISBURY
Fax:		State:	North Carolina
Email:		Postal Code:	28144
Primary Contact			
Contact:	Fink, Cindy	Work:	
Email:	cfink@mowrowan.org	Cell:	919-691-7323

Inspection Type:	General Inspection
------------------	--------------------

Violation Code	Days to Correct*	Violation	Notes	Location
906.2	29	Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10. Exceptions: 1.The distance of travel to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies. 2.Thirty-day inspections shall not be required for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met: 2.1.Electronic monitoring shall confirm that extinguishers are positioned, charged and unobstructed. 2.2.Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal. 2.3.The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment. 2.4.Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed. 2.5.A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10. 3.In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations.	The fire extinguishers were last inspected 09/2020. Fire extinguishers are required to be inspected annually in accordance with NFPA 10.	Fire extinguishers
1004.3	29	Posting of occupant loading shall be in accordance with Section 204.11.2 of the North Carolina Administrative Code and Policies.	Because the building is an assembly occupancy an occupant load sign is needed. Occupant load for the dining/meeting room is 133 for tables and chairs.	Occupant load sign needed.
1013.1	29	Exits and exit access doors shall be marked by an approved exit sign readily visible from any direction of egress travel. The path of egress travel to exits and within exits shall be marked by readily visible exit signs to clearly indicate the direction of egress travel in cases where the exit or the path of egress travel is not immediately visible to the occupants. Intervening means of egress doors within exits shall be marked by exit signs. Exit sign placement shall be such that no point in an exit access corridor or exit passageway is more than 100 feet (30 480 mm) or the listed viewing distance for the sign, whichever is less, from the nearest visible exit sign. Exceptions: 1.Exit signs are not required in rooms or areas that require only one exit or exit access. 2.Main exterior exit doors or gates that are obviously and clearly identifiable as exits need not have exit signs where approved by the fire code official. 3.Exit signs are not required in occupancies in Group U and individual sleeping units or dwelling units in Group R-1, R-2 or R-3. 4.Exit signs are not required in dayrooms, sleeping rooms or dormitories in occupancies in Group I-3. 5.In occupancies in Groups A-4 and A-5, exit signs are not required on the seating side of vomitories or openings into seating areas where exit signs are provided in the concourse that are readily apparent from the vomitories. Egress lighting is provided to identify each vomitory or opening within the seating area in an emergency.	Exits signs are needed above the exit doors.	Exit signs needed above exit doors

Inspection Notes:

Inspector : John McCartney

A handwritten signature in blue ink, appearing to read "John D. McArthur", is centered within a rectangular box.

* Number of days to correct from date inspected.

A variance procedure is available. Please contact the inspector named for further assistance with this or any other matter.